





Spillway DWR
17-CA-CDF-000114
02/23/2017
0600 - 0600
NAD83

- ICP
- Drop Point
- Monitor_Camera_Locations
- Culvert
- Road
- Haul Route
- Potential Stockpile
- Concrete
- Crane
- Heli-Rock bags
- Large Rock
- Rip Rap
- Monitor_Path_Locations
- Monitor_Path_FCO_Bridge_Deck
- Monitor_Path_FCO_Rovers_Spillway_Emb
- Monitor_Path_Thermalito_Diversion_Dam
- Gated Spillway
- Monitor_MCOM_Trailer
- Monitor_Path_ORO_Road
- Power Lines
- Emergency Flow Path
- Emergency Spillway Area
- Sensitive Resource Areas



IMT 3 GIS
 February 22, 2017
 1538 Hours



-Monitor Camera
 -Monitor Path Location
 -Monitor Path FCO Bridge Deck
 -Monitor MCOM Trailer
 -Monitor Path FCO Rovers Left & Right Spillway Embankment

-Monitor Path Location
 -Monitor Path Thermalito Diversion Dam

-Monitor Camera
 -Monitor Path Location
 -Monitor Path ORO Road

ICP

162