



# Suppression Repair


## Mendocino Complex

CA-MEU 008674

River Fire

August 8, 2018

- FOBS : Structure Lost
- GPS verified, no assessment
- Assessed, No repair
- Identified for Repair
- SWAG line
- Active Mines (2010)
- Scott (2012) Dozer Line
- North (2012) Dozer Line
- Equipment Avoidance Areas
- Chipping Slash
- Culvert Damage
- Dozer Push
- Fence Damage
- Gate
- Hazard Tree
- Meadow Damage
- Other
- Road Needs Repair
- Water Course Crossing
- Waterbar Needed



Miles  
0 0.5 1 2

1:100,000

IMT 2 GIS  
August 08, 2018  
0444

