



Suppression Repair

Mendocino Complex
CA-MEU 008674
River Fire
August 11, 2018

Suppression Repair
Grey = Complete

- Chipping Slash
- Culvert Damage
- Dozer Push
- Fence Damage
- Gate
- Meadow Damage
- Other
- Road Needs Repair
- Water Course Crossing
- Waterbar Needed

- # FOBS : Structure Damaged
- " FOBS : Structure Lost
- GPS verified, no assessment
- Assessed, No repair
- Identified for Repair
- SWAG line
- Completed



Miles
0 0.5 1 2

1:100,000

IMT 2 GIS
August 11, 2018
0300

