



- Suppression Repair**  
**Grey = Completed**
- FOBS : Structure Lost
  - ▲ FOBS : Structure Damaged
  - READ SR pts
  - READ SR Lines
- Suppression Repair Points**
- Bridge
  - Cattleguard Damage
  - Chipping Slash
  - Culvert Damage
  - Drop Point
  - Dozer Push
  - Fence Damage
  - Equipment Found
  - Gate
  - Hand Line Repair
  - Hazard Tree
  - Helispot
  - Lop and Scatter Trees
  - Meadow Damage
  - Other
  - Road Needs Repair
  - Retardant Track Point
  - Retardant Avoidance Area
  - Safety Zone
  - Staging Area
  - Water Course Crossing
  - Water Drafting Location
  - Waterbar Needed
- Suppression Repair Lines**
- FOBS verified, no assessment
  - Assessed, No repair
  - Identified for Repair
  - SWAG line
  - Completed

**Suppression Repair**

**Mendocino Complex Ranch Fire**  
**CA-MEU 008674**  
**8/13/2018**

**Mendocino Complex**  
**Suppression Repair**  
**Ranch Fire Overview**  
**CA-MEU 008674**

**1:72,000**  
**Team 2 GIS**  
**NAD 83**

Produced: 8/13/2018  
 1:58:49 AM

**Suppression Repair**

**Mendocino Complex**  
**Ranch Fire**  
**CA-MEU 008674**  
**8/13/2018**

Division Break

Branch Break

Dip Site

Drop Point

Helibase

Incident Command Post

Mobile Weather Unit

Repeater

Staging Area

Uncontrolled Fire Edge

Completed Line

Completed Dozer Line

Completed Hand Line

Road as Completed Line

Proposed Dozer Line

Wildfire Daily Fire Perimeter

Local Government

CA Dept. of Parks and Recreation

CA Dept. of Fish and Wildlife

Other State Lands

USDA Forest Service

Bureau of Land Management

Bureau of Indian Affairs