



- Suppression Repair**
- Suppression Repair Grey = Completed
 - READ SR pts
 - READ SR Lines
 - FOBS: Structure Lost
 - Suppression Repair Points
 - Chipping Slash
 - Dozer Push
 - Fence Damage
 - Other
 - Water Course Crossing
 - Waterbar Needed
 - Suppression Repair Lines
 - FOBS verified, no assessment
 - Identified for repair
 - SRWD line

<p>Suppression Repair</p> <p>Mendocino Complex DIV Q CA-MEU-008674 August 18, 2018</p>	<p>Division Break — Completed Line</p> <p>Branch Break — Completed Dozer Line</p> <p>Dip Site</p> <p>Drop Point</p> <p>DPA Boundary</p> <p>Active Mines (2010)</p>		<p>Mendocino Complex Suppression Repair DIV Q CA-MEU-008674</p>		<p>Local Government</p> <p>CA Dept. of Fish and Wildlife</p> <p>USDA Forest Service</p> <p>Bureau of Land Management</p> <p>Bureau of Indian Affairs</p>	<p>Suppression Repair</p> <p>Mendocino Complex DIV Q CA-MEU-008674 August 18, 2018</p>
---	--	--	---	--	--	---

1:13,200
NAD 83

Produced: 8/18/2018
1:02:56 AM