

Suppression Repair GRAY = COMPLETED


Suppression Repair Points

- Bridge
- Cattleguard Damage
- Chipping Slash
- Culvert Damage
- Dozer Push
- Drop Point
- Equipment Found
- Fence Damage
- Gate
- Hand Line Repair
- Hazard Tree
- Helispot
- Lop and Scatter Trees
- Meadow Damage
- Other
- Retardant Avoidance Area
- Retardant Track Point
- Road Needs Repair
- Safety Zone
- Staging Area
- Water Course Crossing
- Water Drafting Location
- Waterbar Needed

Suppression Repair Status Masking

- GPS Verified - No Assessment
- Not GPS Verified - No Assessment
- Repair Needed
- Completed - Needs READ Approval
- Completed - Approved

- READ: Points
- READ: Lines
- FOBS: Structure Damaged
- FOBS: Structure Lost



Suppression Repair
Mendocino Complex Ranch Fire - Div. C/D
CA-MEU-008674
8/21/2018

Uncontrolled Fire Edge	Helispot	Direct Protection Areas
Contained Fire Edge	Dip Site	Bridge (w weight limit)
Completed Dozer Line	Mobile Retardant Base	Active Mines (2010)
Completed Hand Line	Water Source	
Road as Completed Line	Repeater	
Staging Area	Mobile Weather Unit	
Drop Point		

Mendocino Complex
CA-MEU-008674
Suppression Repair
Ranch Fire - Div. C/D
August 21, 2018

Ownership

- Other State Lands
- USDA Forest Service

NAD83 UTM Zone 10
Contour Interval: 40 ft.
 Produced: 8/21/2018 1:29:21 AM

0 0.25 0.5 0.75 Miles