



**Suppression Repair GRAY = COMPLETED**

Suppression Repair Points		Suppression Repair Status Masking	
	Bridge		GPS Verified - No Assessment
	Cattleguard Damage		Not GPS Verified - No Assessment
	Chipping Slash		Repair Needed
	Culvert Damage		Completed - Needs READ Approval
	Dozer Push		Completed - Approved
	Drop Point		READ Points
	Equipment Found		READ Lines
	Fence Damage		FOBS: Structure Damaged
	Gate		FOBS: Structure Lost
	Hand Line Repair		Lop and Scatter Trees
	Hazard Tree		Meadow Damage
	Helispot		Other
	Completed Dozer Line		Retardant Avoidance Area
	Completed Hand Line		Retardant Track Point
	Road as Completed Line		Road Needs Repair
	Active Mines (2010)		Safety Zone
	Direct Protection Areas		Staging Area
			Water Course Crossing
			Water Drafting Location
			Waterbar Needed

**Suppression Repair**

Mendocino Complex Ranch Fire - Div. Q  
CA-MEU-008674  
8/21/2018

	Contained Fire Edge		Branch Break		Helispot
	Completed Dozer Line		Division Break		Dip Site
	Completed Hand Line		Incident Command Post		Mobile Retardant Base
	Road as Completed Line		Camp		Water Source
	Active Mines (2010)		Staging Area		Repeater
	Direct Protection Areas		Drop Point		Mobile Weather Unit

**Mendocino Complex Ranch Fire - Div. Q**

CA-MEU-008674  
Suppression Repair  
August 21, 2018

**Mendocino Complex Ranch Fire - Div. Q**

CA-MEU-008674  
Suppression Repair  
August 21, 2018

**Ownership**

- Local Government
- Other State Lands
- USDA Forest Service
- Bureau of Land Management
- Bureau of Indian Affairs

NAD83 UTM Zone 10  
Contour Interval: 40 ft.  
Produced: 8/21/2018 1:05:30 AM

0 0.25 0.5 0.75 1 Miles

**Suppression Repair**

Mendocino Complex Ranch Fire - Div. Q  
CA-MEU-008674  
8/21/2018