



Suppression Repair GRAY = COMPLETED

Suppression Repair Points		Suppression Repair Status Masking	
	Bridge		GPS Verified - No Assessment
	Cattleguard Damage		Not GPS Verified - No Assessment
	Chipping Slash		Repair Needed
	Culvert Damage		Completed - Needs READ Approval
	Dozer Push		Completed - Approved
	Drop Point		Road Needs Repair
	Equipment Found		Safety Zone
	Fence Damage		Staging Area
	Gate		Water Course Crossing
	Hand Line Repair		Water Drafting Location
	Hazard Tree		Waterbar Needed
	Helispot		READ Points
	Lop and Scatter Trees		READ Lines
	Meadow Damage		FOBS: Structure Damaged
	Other		FOBS: Structure Lost
	Retardant Avoidance Area		
	Retardant Track Point		

Suppression Repair

Mendocino Complex Ranch Fire - Div. R CA-MEU-008674
8/21/2018

	Contained Fire Edge		Helispot
	Completed Dozer Line		Dip Site
	Completed Hand Line		Mobile Retardant Base
	Road as Completed Line		Water Source
	Bridge (w/ weight limit)		Repeater
	Direct Protection Areas		Mobile Weather Unit
	Branch Break		
	Division Break		
	Incident Command Post		
	Camp		
	Staging Area		
	Drop Point		



Mendocino Complex
CA-MEU-008674
Suppression Repair
Ranch Fire - Div. R
August 21, 2018

Ownership

	Local Government
	CA Dept. of Fish and Wildlife
	USDA Forest Service
	Bureau of Land Management
	Bureau of Indian Affairs

NAD83 UTM Zone 10
Contour Interval: 40 ft.
Produced: 8/21/2018 1:17:12 AM

0 0.25 0.5 0.75 Miles

Suppression Repair

Mendocino Complex Ranch Fire - Div. R CA-MEU-008674
8/21/2018