



- Suppression Repair Points**
- Bridge
 - Cattleguard Damage
 - Chipping Slash
 - Culvert Damage
 - Dozer Push
 - Drop Point
 - Equipment Found
 - Fence Damage
 - Gate
 - Hand Line Repair
 - Hazard Tree
 - Helispot
 - Lop and Scatter Trees
 - Meadow Damage
 - Other
 - Retardant Avoidance Area
 - Retardant Track Point
 - Road Needs Repair
 - Safety Zone
 - Staging Area
 - Water Course Crossing
 - Water Drafting Location
 - Waterbar Needed
- GRAY = COMPLETED**

Suppression Repair
 Mendocino Complex Ranch Fire - Div. Q
 CA-MEU-008674
 8/25/2018

- Contained Fire Edge
- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Active Mines (2010)
- Direct Protection Areas
- Zone Break
- Branch Break
- Division Break
- Incident Command Post
- Camp
- Staging Area
- Drop Point
- Helispot
- Dip Site
- Mobile Retardant Base
- Water Source
- Repeater
- Mobile Weather Unit



Mendocino Complex
 CA-MEU-008674
 Suppression Repair
 Ranch Fire - Div. Q
 August 25, 2018

- Ownership**
- Local Government
 - USDA Forest Service
 - Other State Lands
 - Bureau of Land Management



NAD83 UTM Zone 10
 Contour Interval: 40 ft.
 Produced: 8/25/2018 11:10:48 AM

Suppression Repair
 Mendocino Complex Ranch Fire - Div. Q
 CA-MEU-008674
 8/25/2018