



Suppression Repair GRAY = COMPLETED

Suppression Repair Points		Suppression Repair Status Masking	
	Bridge		GPS Verified - No Assessment
	Cattleguard Damage		Not GPS Verified - No Assessment
	Chipping Slash		Repair Needed
	Culvert Damage		Completed - Needs READ Approval
	Dozer Push		Completed - Approved
	Drop Point		READ Points
	Equipment Found		READ Lines
	Fence Damage		
	Gate		
	Hand Line Repair		
	Hazard Tree		
	Helispot		
	Lop and Scatter Trees		
	Meadow Damage		
	Other		
	Retardant Avoidance Area		
	Retardant Track Point		
	Road Needs Repair		
	Safety Zone		
	Staging Area		
	Water Course Crossing		
	Water Drafting Location		
	Waterbar Needed		

Suppression Repair
Mendocino Complex Ranch Fire - Div. E/F
CA-MEU-008674
8/26/2018

	Uncontrolled Fire Edge		Drop Point		Direct Protection Areas
	Contained Fire Edge		Helispot		Wilderness Area
	Completed Dozer Line		Dip Site		
	Completed Hand Line		Mobile Retardant Base		
	Road as Completed Line		Water Source		
	Incident Command Post		Repeater		
	Camp		Mobile Weather Unit		
	Staging Area		Bridge (w/ weight limit)		

Mendocino Complex
CA-MEU-008674
Suppression Repair
Ranch Fire - Div. E/F
August 26, 2018

Ownership

-
-

NAD83 UTM Zone 10
 Contour Interval: 40 ft.
 Produced: 8/25/2018 11:39:03 PM

0 0.25 0.5 0.75 1.20,000
 Miles

Suppression Repair
Mendocino Complex Ranch Fire - Div. E/F
CA-MEU-008674
8/26/2018