



Suppression Repair GRAY = COMPLETED

Suppression Repair Points		Suppression Repair Status Masking	
	Bridge		GPS Verified - No Assessment
	Cattleguard Damage		Not GPS Verified - No Assessment
	Chipping Slash		Repair Needed
	Culvert Damage		Completed - Needs READ Approval
	Dozer Push		Completed - Approved
	Drop Point		READ Points
	Equipment Found		Roads Needed Repair
	Fence Damage		Safety Zone
	Gate		Staging Area
	Hand Line Repair		Water Course Crossing
	Hazard Tree		Water Drafting Location
	Helispot		Waterbar Needed

Suppression Repair

Mendocino Complex Ranch Fire - Div. H/I
CA-MEU-008674
8/26/2018

Mendocino Complex
CA-MEU-008674
Suppression Repair
Ranch Fire - Div. H/I
August 26, 2018

Suppression Repair

Mendocino Complex Ranch Fire - Div. H/I
CA-MEU-008674
8/26/2018

Ownership

- Other State Lands
- USDA Forest Service
- Bureau of Land Management

NAD83 UTM Zone 10
Contour Interval: 40 ft.
Produced: 8/26/2018 2:15:21 AM

0 0.25 0.5 0.75 1.20,000 Miles