



Suppression Repair GRAY = COMPLETED

Suppression Repair Points		Suppression Repair Status Masking	
	Bridge		GPS Verified - No Assessment
	Cattleguard Damage		Not GPS Verified - No Assessment
	Chipping Slash		Repair Needed
	Culvert Damage		Completed - Needs READ Approval
	Dozer Push		Completed - Approved
	Drop Point		READ Points
	Equipment Found		READ Lines
	Fence Damage		
	Gate		
	Hazard Tree		
	Helispot		
	Lop and Scatter Trees		
	Meadow Damage		
	Other		
	Retardant Avoidance Area		
	Retardant Track Point		
	Road Needs Repair		
	Safety Zone		
	Staging Area		
	Water Course Crossing		
	Water Drafting Location		
	Waterbar Needed		

Suppression Repair

Mendocino Complex Ranch Fire - Div. E/F
CA-MEU-008674
8/27/2018

Suppression Repair

Mendocino Complex Ranch Fire - Div. E/F
CA-MEU-008674
8/27/2018

Mendocino Complex
CA-MEU-008674
Suppression Repair
Ranch Fire - Div. E/F
August 27, 2018

Suppression Repair

Mendocino Complex Ranch Fire - Div. E/F
CA-MEU-008674
8/27/2018

Ownership

Other State Lands

USDA Forest Service

0 0.25 0.5 0.75 1.20,000 Miles

NAD83 UTM Zone 10
Contour Interval: 40 ft.
Produced: 8/26/2018 11:29:19 PM

Suppression Repair

Mendocino Complex Ranch Fire - Div. E/F
CA-MEU-008674
8/27/2018