

# West Zone

# East Zone

# South Zone

**Suppression Repair**  
Gray = Completed

**Suppression Repair Lines**

- GPS Verified - No Assessment
- Not GPS Verified - No Assessment
- Repair Needed
- Completed - Needs READ Approval
- Completed - Approved

RANCH FIRE DOZER LINE SUPPRESSION REPAIR PROGRESS			
Dozer Line Constructed:	1406188	feet	266.32 Miles
Dozer Line Repaired :	1144231	feet	216.71 Miles
Percentage of Dozer Line Repaired:	81%		

**Suppression Repair**

**Mendocino Complex Ranch Fire Overview CA-MEU-008674 8/28/2018**

- Uncontrolled Fire Edge
- Contained Fire Edge
- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Proposed Dozer Line
- ZoneBreakLines
- Zone Break
- Branch Break
- Division Break
- Incident Command Post
- Camp
- Staging Area
- Drop Point
- Helispot
- Dip Site
- Water Source
- Repeater
- Mobile Weather Unit

## Mendocino Complex CA-MEU-008674 Suppression Repair Ranch Fire Overview August 28, 2018

**Ownership**

- Local Government
- CA Dept. of Parks and Recreation
- CA Dept. of Fish and Wildlife
- Other State Lands
- USDA Forest Service
- Bureau of Reclamation
- Bureau of Land Management
- Bureau of Indian Affairs
- Department of Defense
- Other Federal Lands
- Bridge (w/ weight limit)
- Active Mines (2010)
- Mercury Mines
- Equipment Avoidance Areas
- Life Hazard Zone
- Direct Protection Areas
- Wilderness Area

**Suppression Repair**

**Mendocino Complex Ranch Fire Overview CA-MEU-008674 8/28/2018**

NAD83 UTM Zone 10  
Contour Interval: 200 ft.  
Produced: 8/27/2018 11:38:30 PM  
0 0.5 1 2 Miles  
1:73,000