



- Suppression Repair Gray = Completed**
- Suppression Repair Points**
- Point Type: Repair Status
 - House Repair Needed
 - Clearing Slash Repair Needed
 - Clearing Slash Completed - Approved
 - Current Damage, Repair Needed
 - Current Damage, Completed - Approved
 - Clear Path, Repair Needed
 - Clear Path, Completed - Approved
 - Drop Point, Repair Needed
 - Drop Point, Completed - Approved
 - Equipment Fault, Repair Needed
 - Face Damage, Repair Needed
 - Face Damage, Completed - Approved
 - Gas, Repair Needed
 - Gas, Completed - Approved
 - Hazard Tree, Repair Needed
 - Hazard Tree, Completed - Approved
 - Hazardous, Repair Needed
 - Log and Scatter Trees, Repair Needed
 - Meadow Damage, Repair Needed
 - Other, Repair Needed
 - Other, Completed - Approved
 - Rebarment Track Point, Repair Needed
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Course Crossing, Obstructed
 - Water Course Crossing, Completed - Approved
 - Water Drafting Location, Repair Needed
 - Water Drafting Location, Completed - Approved
 - Waterbar, Repair Needed
 - Waterbar, Completed - Approved
- Suppression Repair Lines**
- Point Status
 - GPS Verified - No Assessment
 - Not GPS Verified - No Assessment
 - Repair Needed
 - Completed - Needs ROAD Approval
 - Completed - Approved

Suppression Repair

Div C
Mendocino Complex
CA-MEU-008674
September 1, 2018

Mendocino Complex - Div C

CA-MEU-008674
September 1, 2018

Road Class shown in fuchsia
Not all roads show Road Class values

- Contained Fire Edge
- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Direct Protection Areas
- Ownership: Other State Lands, USDA Forest Service
- Bridge (w weight limit)
- Active Mines (2010)

Produced: 10:42:26 PM 09/01/2018
NAD83 UTM Zone 10N

Suppression Repair

Div C
Mendocino Complex
CA-MEU-008674
September 1, 2018