



Suppression Repair Points		Suppression Repair Lines	
	Bridge		GPS Verified - No Assessment
	Cattleguard Damage		Not GPS Verified - No Assessment
	Chipping Slash		Repair Needed
	Culvert Damage		Completed - Needs READ Approval
	Dozer Push		Completed - Approved
	Drop Point		
	Equipment Found		
	Fence Damage		
	Gate		
	Hand Line Repair		
	Hazard Tree		
	Helispot		
	Lop and Scatter Trees		
	Meadow Damage		
	Other		
	Retardant Avoidance Area		
	Retardant Track Point		
	Road Needs Repair		
	Safety Zone		
	Staging Area		
	Water Course Crossing		
	Water Drafting Location		
	Waterbar Needed		

GRAY = COMPLETED

<p>Suppression Repair</p> <p>Mendocino Complex River Fire - Div K/L CA-MEU-008674 9/1/2018</p>	<p> Uncontrolled Fire Edge</p> <p> Contained Fire Edge</p> <p> Completed Dozer Line</p> <p> Completed Hand Line</p> <p> Road as Completed Line</p> <p> Zone Break</p> <p> Branch Break</p> <p> Division Break</p> <p> Incident Command Post</p> <p> Camp</p> <p> Staging Area</p> <p> Drop Point</p> <p> Helispot</p> <p> Dip Site</p> <p> Mobile Retardant Base</p> <p> Water Source</p> <p> Repeater</p> <p> Mobile Weather Unit</p> <p> Direct Protection Areas</p> <p> Wilderness Area</p> <p> Bridge (w/ weight limit)</p>	<p>Mendocino Complex CA-MEU-008674 Suppression Repair Ranch Fire - Div K/L September 1, 2018</p>	<p>Ownership</p> <ul style="list-style-type: none"> Other State Lands USDA Forest Service Bureau of Land Management Bureau of Indian Affairs Other Federal Lands 			<p>NAD83 UTM Zone 10 Contour Interval: 40 ft. Produced: 8/31/2018 9:46:36 PM</p> <p>0 0.25 0.5 0.75 1.20,000 Miles</p>
---	---	--	---	--	--	--