



- Suppression Repair Gray = Completed**
- Suppression Repair Points**
- Pointy Repair Status
 - Chipping Station, Repair Needed
 - Chipping Station, Completed - Approved
 - Clearcut Damage, Repair Needed
 - Clearcut Damage, Completed - Approved
 - Dozer Push, Repair Needed
 - Dozer Push, Completed - Approved
 - Drop Point, Repair Needed
 - Equipment Front, Repair Needed
 - Fence Damage, Repair Needed
 - Fence Damage, Completed - Approved
 - Gas, Repair Needed
 - Gas, Completed - Approved
 - Hazard Tree, Repair Needed
 - Hazard Tree, Completed - Approved
 - Hotspot, Repair Needed
 - Log and Scatter Trees, Repair Needed
 - Meadow Damage, Repair Needed
 - Other, Repair Needed
 - Other, Completed - Approved
 - Repaired Track Flank, Repair Needed
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Drafting Location, Repair Needed
 - Water Needed, Repair Needed
 - Water Needed, Completed - Approved
- Suppression Repair Lines**
- Point Status
 - GPS Verified - No Assessment
 - Not GPS Verified - No Assessment
 - Repair Needed
 - Completed - Needs READ Approval
 - Completed - Approved

Suppression Repair
Div H
Mendocino Complex
CA-MEU-008674
September 3, 2018

0 0.25 0.5 1 Miles

Produced: 9/24/18 PM 9/2/2018
 NAD83 UTM Zone 10N
 1:15,000



Suppression Repair - Div H
Mendocino Complex
CA-MEU-008674
September 3, 2018

Road Class shown in fuschia
 Not all roads show Road Class values

- Contained Fire Edge
- Completed Dozer Line
- Completed Hand Line
- Completed Line
- Road as Completed Line
- Bridge (w/ weight limit)
- Direct Protection Areas
- Wilderness Area
- Rehab Avoidance Area
- Overship
- USDA Forest Service

Suppression Repair
Div H
Mendocino Complex
CA-MEU-008674
September 3, 2018