



- Suppression Repair Gray = Completed**
- Suppression Repair Points**
- Point Type: Repair Status
  - Chipping Station: Repair Needed
  - Chipping Station: Completed - Approved
  - Clearcut Damage: Repair Needed
  - Clearcut Damage: Completed - Approved
  - Dozer Path: Repair Needed
  - Dozer Path: Completed - Approved
  - Drip Point: Repair Needed
  - Equipment Failure: Repair Needed
  - Fence Damage: Repair Needed
  - Fence Damage: Completed - Approved
  - Gate: Repair Needed
  - Gate: Completed - Approved
  - Hazard Tree: Repair Needed
  - Handcut: Repair Needed
  - Log and Scatter Trees: Repair Needed
  - Meadow Damage: Repair Needed
  - Other: Repair Needed
  - Other: Completed - Approved
  - Rehabilitation Track Point: Repair Needed
  - Road Needs Repair: Repair Needed
  - Road Needs Repair: Completed - Approved
  - Water Course Crossing: Repair Needed
  - Water Course Crossing: Completed - Approved
  - Water Drafting Location: Repair Needed
  - Waterline Needs: Repair Needed
  - Waterline Needs: Completed - Approved
- Suppression Repair Lines**
- Point Status
  - Not GPS Verified - No Assessment
  - Not GPS Verified - No Assessment
  - Repair Needed
  - Completed - Needs READ Approval
  - Completed - Approved

**Suppression Repair**

**Div J**

**Mendocino Complex**

**CA-MEU-008674**

**September 3, 2018**

Produced: 9/23/18 PM 9/23/2018

NAD83 UTM Zone 10N

**Suppression Repair - Div J**

**Mendocino Complex**

**CA-MEU-008674**

**September 3, 2018**

Road Class shown in fuschia

Not all roads show Road Class values

**Ownership**

- Other State Lands
- USDA Forest Service
- Bureau of Reclamation
- Bureau of Land Management
- Other Federal Lands

**Suppression Repair**

- Contained Fire Edge
- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Direct Protection Areas
- Wilderness Area
- Rehab Avoidance Area

**Suppression Repair**

**Div J**

**Mendocino Complex**

**CA-MEU-008674**

**September 3, 2018**