



- Suppression Repair**
Gray = Completed
- Suppression Repair Points**
- Fireline Repair Status
 - Chipping Station, Repair Needed
 - Chipping Station, Completed - Approved
 - Clearcut Damage, Repair Needed
 - Clearcut Damage, Completed - Approved
 - Dozer Path, Repair Needed
 - Dozer Path, Completed - Approved
 - Drip Point, Repair Needed
 - Equipment Fault, Repair Needed
 - Fence Damage, Repair Needed
 - Fence Damage, Completed - Approved
 - Gate, Repair Needed
 - Gate, Completed - Approved
 - Hazard Tree, Repair Needed
 - Hazard Tree, Completed - Approved
 - Log and Scatter Trees, Repair Needed
 - Meadow Damage, Repair Needed
 - Other, Repair Needed
 - Other, Completed - Approved
 - Hardware Track Point, Repair Needed
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Drafting Location, Repair Needed
 - Water Needed, Repair Needed
 - Water Needed, Completed - Approved
- Suppression Repair Lines**
- Repair Status
 - GPS Verified - No Assessment
 - Not GPS Verified - No Assessment
 - Repair Needed
 - Completed - Needs READ Approval
 - Completed - Approved

Suppression Repair
 Div L
 Mendocino Complex
 CA-MEU-008674
 September 3, 2018

1:15,000
 Produced: 9/4/2018 10:43:27 PM
 9/2/2018
 0 0.25 0.5 1 Miles
 NAD83 UTM Zone 10N



Suppression Repair - Div L
Mendocino Complex
CA-MEU-008674
September 3, 2018

- Road Class shown in fuchsia
 Not all roads show Road Class values
- Uncontrolled Fire Edge
 - Contained Fire Edge
 - Completed Dozer Line
 - Completed Hand Line
 - Road as Completed Line
 - Bridge (w/ weight limit)
 - Ownership
 - USDA Forest Service
 - Bureau of Reclamation
 - Bureau of Land Management
 - Other Federal Lands
 - Direct Protection Areas
 - Wilderness Area
 - Rehab Avoidance Area

Suppression Repair
 Div L
 Mendocino Complex
 CA-MEU-008674
 September 3, 2018