


- Suppression Repair Gray = Completed**
- PointType: Repair Status**
- Bridge Repair Needed
  - Clearing Slash Repair Needed
  - Clearing Slash Completed - Approved
  - Culvert Damage Repair Needed
  - Culvert Damage Completed - Approved
  - Clear Path Repair Needed
  - Clear Path Completed - Approved
  - Drop Point Repair Needed
  - Equipment Failure Repair Needed
  - Fence Damage Repair Needed
  - Fence Damage Completed - Approved
  - Gate Repair Needed
  - Gate Completed - Approved
  - Hazard Tree Repair Needed
  - Hazard Repair Needed
  - Log and Snags Trees Repair Needed
  - Meadow Damage Repair Needed
  - Other - Sub
  - Other Repair Needed
  - Other Completed - Approved
  - Reservoir Tank Flank Repair Needed
  - Road Needs Repair Repair Needed
  - Road Needs Repair Completed - Approved
  - Water Course Crossing - Sub
  - Water Course Crossing Repair Needed
  - Water Course Crossing Completed - Approved
  - Water Drafting Location Repair Needed
  - Waterbar Repair Needed
  - Waterbar Completed - Approved
- Suppression Repair Lines**
- PointType: Status**
- GPS Verified - No Assessment
  - Not GPS Verified - No Assessment
  - Repair Needed
  - Completed - Needs READ Approval
  - Completed - Approved

Suppression Repair  
 Div H  
 Mendocino Complex  
 CA-MEU-008674  
 September 5, 2018



Produced:  
 10/27/18 PM  
 9/4/2018



NAD83 UTM Zone 10N



**Suppression Repair - Div H**  
**Mendocino Complex**  
**CA-MEU-008674**  
**September 5, 2018**

Road Class shown in fuchsia  
 Not all roads show Road Class values

- Contained Fire Edge
- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Bridge (w/ weight limit)
- Direct Protection Areas
- Wilderness Area
- Rehab Avoidance Area
- Ownership
- USDA Forest Service

Suppression Repair  
 Div H  
 Mendocino Complex  
 CA-MEU-008674  
 September 5, 2018