


- Suppression Repair Gray = Completed**
- PointType: Repair Status**
- Bridge: Repair Needed
  - Clearing Slash: Repair Needed
  - Clearing Slash: Completed - Approved
  - Current Damage: Repair Needed
  - Current Damage: Completed - Approved
  - Down Pile: Repair Needed
  - Down Pile: Completed - Approved
  - Drip Point: Repair Needed
  - Equipment Failure: Repair Needed
  - Fence Damage: Repair Needed
  - Fence Damage: Completed - Approved
  - Gate: Repair Needed
  - Gate: Completed - Approved
  - Hazard Tree: Repair Needed
  - Hazard Tree: Completed - Approved
  - Log and Snags: Repair Needed
  - Meadow Damage: Repair Needed
  - Other: Repair Needed
  - Other: Completed - Approved
  - Rebarbed Track Pile: Repair Needed
  - Road Needs Repair: Repair Needed
  - Road Needs Repair: Completed - Approved
  - Water Course Crossing: Repair Needed
  - Water Course Crossing: Completed - Approved
  - Water Course Crossing: Other
  - Water Drafting Location: Repair Needed
  - Waterbar: Repair Needed
  - Waterbar: Completed - Approved
- Suppression Repair Lines**
- GPS Verified - No Assessment
  - Not GPS Verified - No Assessment
  - Repair Needed
  - Completed - Needs ROAD Approval
  - Completed - Approved



**Suppression Repair**

**Div I**  
Mendocino Complex  
CA-MEU-008674  
September 5, 2018





Produced: 9/4/2018 9:49:51 PM  
9/4/2018

1:15,000

0 0.25 0.5 1 Miles

NAD83 UTM Zone 10N

**Suppression Repair - Div I**  
**Mendocino Complex**  
**CA-MEU-008674**  
**September 5, 2018**

Road Class shown in fuschia  
Not all roads show Road Class values

**Ownership**

- USDA Forest Service
- Bureau of Reclamation
- Bureau of Land Management
- Bureau of Indian Affairs
- Other Federal Lands

**Suppression Repair**

**Div I**  
Mendocino Complex  
CA-MEU-008674  
September 5, 2018

- Contained Fire Edge
- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Direct Protection Areas
- Rehab Avoidance Area