



- Suppression Repair Points**
- PointType, Repair Status
- Ridge, Repair Needed
 - Chipping Blows, Repair Needed
 - Culvert Damage, Repair Needed
 - Culvert Damage, Completed - Approved
 - Clear Push, Repair Needed
 - Clear Push, Completed - Approved
 - Drop Point, Repair Needed
 - Equipment Failure, Repair Needed
 - Fence Damage, Repair Needed
 - Fence Damage, Completed - Approved
 - Gate, Repair Needed
 - Gate, Completed - Approved
 - Hazard Tree, Repair Needed
 - Helipad, Repair Needed
 - Log and Scatter Trees, Repair Needed
 - Machine Damage, Repair Needed
 - Other, Repair Needed
 - Other, Completed - Approved
 - Rebarbed Track Floor, Repair Needed
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Crossing Location, Repair Needed
 - Water Crossing Location, Completed - Approved
 - Waterbar, Repair Needed
 - Waterbar, Completed - Approved



Road Class shown in fuchsia. Not all roads show Road Class values

SUPPRESSION REPAIR, 09/06/18 Div F/G



SoCal IMT 3 GIS
September 05, 2018
2338
Datum: NAD 83



Mendocino Complex
CA-MEU-008674
September 6, 2018
SUPPRESSION REPAIR
Div F/G

Repair Legend

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

- Contained Fire Edge
- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Direct Protection Areas
- Wilderness Area
- Rehab Avoidance Area
- Bridge (w/ weight limit)

Ownership

- USDA Forest Service