


- Suppression Repair Points**
- Point Type, Repair Status
  - Ridge Repair Needed
  - Chipping Blows Repair Needed - Approved
  - Culvert Damage Repair Needed
  - Culvert Damage Completed - Approved
  - Clear Push Repair Needed
  - Clear Push Completed - Approved
  - Clear Pile Repair Needed
  - Clear Pile Completed - Approved
  - Drop Point Repair Needed
  - Equipment Failure Repair Needed
  - Fence Damage Repair Needed
  - Fence Damage Completed - Approved
  - Gate Repair Needed
  - Gate Completed - Approved
  - Hazard Tree Repair Needed
  - Hazard Tree Completed - Approved
  - Log and Scatter Trees Repair Needed
  - Machine Damage Repair Needed
  - Machine Damage Completed - Approved
  - Other Repair Needed
  - Other Completed - Approved
  - Rebarbed Track Pile Repair Needed
  - Road Needs Repair Repair Needed
  - Road Needs Repair Completed - Approved
  - Water Course Crossing Repair Needed
  - Water Course Crossing Completed - Approved
  - Water Course Crossing Repair Needed
  - Water Course Crossing Completed - Approved
  - Watering Location Repair Needed
  - Watering Location Completed - Approved
  - Watering Location Repair Needed
  - Watering Location Completed - Approved



Road Class shown in fuschia. Not all roads show Road Class values

SUPPRESSION REPAIR\_09/06/18  
Div I

SoCal IMT 3 GIS  
September 05, 2018  
2335

QR Code

Miles  
0 0.25 0.5 1

Datum: NAD 83



**Mendocino Complex**  
CA-MEU-008674  
September 6, 2018  
**SUPPRESSION REPAIR**  
Div I

- Repair Legend**
- Completed - Inspected
  - Completed - Ready for Inspection
  - In Progress
  - No Repair Needed
  - Other - See Comments
  - Repair Needed
  - Unknown
- Ownership**
- USDA Forest Service
  - Bureau of Reclamation
  - Bureau of Land Management
  - Bureau of Indian Affairs
  - Other Federal Lands
- Other Symbols:**
- Contained Fire Edge
  - Completed Dozer Line
  - Completed Hand Line
  - Road as Completed Line
  - Direct Protection Areas
  - Rehab Avoidance Area