


- Suppression Repair Points**
- Point Type, Repair Status
- Ridge, Repair Needed
 - Chipping Blows, Repair Needed
 - Culvert Damage, Completed - Approved
 - Culvert Damage, Repair Needed
 - Clear Push, Repair Needed
 - Clear Push, Completed - Approved
 - Drop Point, Repair Needed
 - Drop Point, Completed - Approved
 - Equipment Fault, Repair Needed
 - Fence Damage, Repair Needed
 - Fence Damage, Completed - Approved
 - Gate, Repair Needed
 - Gate, Completed - Approved
 - Hazard Tree, Repair Needed
 - Hazard Tree, Repair Needed
 - Log and Scatter Trees, Repair Needed
 - Machine Damage, Repair Needed
 - Other, Repair Needed
 - Other, Completed - Approved
 - Roadwork Track Pile, Repair Needed
 - Roadwork Track Pile, Repair Needed
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Crossing Location, Repair Needed
 - Watercourse Needs, Repair Needed
 - Watercourse Needs, Completed - Approved

Road Class shown in fuchsia. Not all roads show Road Class values

SUPPRESSION REPAIR, 09/06/18 Div J



Miles
0 0.25 0.5 1

Datum: NAD 83



Mendocino Complex
 CA-MEU-008674
 September 6, 2018
SUPPRESSION REPAIR
 Div J

Repair Legend

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

- Contained Fire Edge
- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Direct Protection Areas
- Wilderness Area
- Rehab Avoidance Area

Ownership

- Other State Lands
- USDA Forest Service
- Bureau of Reclamation
- Bureau of Land Management
- Other Federal Lands