



- Suppression Repair Points**
- PointType: Repair Status
 - Edge: Repair Needed
 - Chipping Blank: Repair Needed
 - Chipping Blank: Completed - Approved
 - Covert Damage: Repair Needed
 - Covert Damage: Completed - Approved
 - Clear Push: Repair Needed
 - Clear Push: Completed - Approved
 - Drop Point: Repair Needed
 - Drop Point: Completed - Approved
 - Escarpment Fault: Repair Needed
 - Fence Damage: Repair Needed
 - Fence Damage: Completed - Approved
 - Gate: Repair Needed
 - Gate: Completed - Approved
 - Hazard Tree: Repair Needed
 - Hazard Tree: Completed - Approved
 - Log and Scatter Trees: Repair Needed
 - Machine Damage: Repair Needed
 - Other: Repair Needed
 - Other: Completed - Approved
 - Rebarbed Track Floor: Repair Needed
 - Road Needs Repair: Repair Needed
 - Road Needs Repair: Completed - Approved
 - Water Course Crossing: Repair Needed
 - Water Course Crossing: Completed - Approved
 - Water Course Crossing: Repair Needed
 - Water Course Crossing: Completed - Approved
 - Water Crossing Location: Repair Needed
 - Water Crossing Location: Completed - Approved
 - Waterbar: Repair Needed
 - Waterbar: Completed - Approved

SUPPRESSION REPAIR_09/06/18
Div L

SoCal IMT 3 GIS
September 05, 2018
2:47

Datum: NAD 83



Mendocino Complex
CA-MEU-008674
September 6, 2018
SUPPRESSION REPAIR
Div L

- Repair Legend**
- Completed - Inspected
 - Completed - Ready for Inspection
 - In Progress
 - No Repair Needed
 - Other - See Comments
 - Repair Needed
 - Unknown
- Ownership**
- USDA Forest Service
 - Bureau of Reclamation
 - Bureau of Land Management
 - Other Federal Lands
- Other Legend**
- Uncontrolled Fire Edge
 - Contained Fire Edge
 - Completed Dozer Line
 - Completed Hand Line
 - Road as Completed Line
 - Bridge (w/ weight limit)
 - Direct Protection Areas
 - Wilderness Area
 - Rehab Avoidance Area

Road Class shown in fuchsia. Not all roads show Road Class values

MNF MUST APPROVE BEFORE REPAIRING