




- Suppression Repair Points**
- PointType, Repair Status
- Bridge, Repair Needed
  - Chipping Blank, Repair Needed
  - Chipping Blank, Completed - Approved
  - Culvert Damage, Repair Needed
  - Culvert Damage, Completed - Approved
  - Clear Push, Repair Needed
  - Clear Push, Completed - Approved
  - Drop Point, Repair Needed
  - Drop Point, Completed - Approved
  - Equipment Failure, Repair Needed
  - Equipment Failure, Completed - Approved
  - Fence Damage, Repair Needed
  - Fence Damage, Completed - Approved
  - Gate, Repair Needed
  - Gate, Completed - Approved
  - Hazard Tree, Repair Needed
  - Hazard Tree, Completed - Approved
  - Haulroad, Repair Needed
  - Lip and Scatter Trees, Repair Needed
  - Machine Damage, Repair Needed
  - Other, Repair Needed
  - Other, Completed - Approved
  - Palletized Truck Park, Repair Needed
  - Road Needs Repair, Repair Needed
  - Road Needs Repair, Completed - Approved
  - Water Course Crossing, Repair Needed
  - Water Course Crossing, Completed - Approved
  - Water Drafting Location, Repair Needed
  - Water Drafting Location, Completed - Approved
  - Waterbar, Repair Needed
  - Waterbar, Completed - Approved



Road Class shown in fuchsia. Not all roads show Road Class values

SUPPRESSION REPAIR, 09/07/18 Div F/G



Datum: NAD 83



INTERAGENCY INCIDENT MANAGEMENT

# Mendocino Complex

CA-MEU-008674  
September 7, 2018

## SUPPRESSION REPAIR

### Div F/G

**Repair Legend**

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

- Contained Fire Edge
- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Direct Protection Areas
- Wilderness Area
- Rehab Avoidance Area
- Bridge (w/ weight limit)

**Ownership**

- USDA Forest Service