



- Suppression Repair Points**
- Point Type, Repair Status
 - Bridge, Repair Needed
 - Chipping Blank, Repair Needed
 - Culvert Damage, Repair Needed - Approved
 - Culvert Damage, Completed - Approved
 - Clear Push, Repair Needed
 - Clear Push, Completed - Approved
 - Drop Point, Repair Needed
 - Equipment Failure, Repair Needed
 - Force Damage, Repair Needed
 - Force Damage, Completed - Approved
 - Gate, Repair Needed
 - Gate, Completed - Approved
 - Hazard Tree, Repair Needed
 - Hazard Tree, Repair Needed
 - Lip and Scatter Trees, Repair Needed
 - Miscellaneous Damage, Repair Needed
 - Other, Repair Needed
 - Other, Completed - Approved
 - Fireline Track Pile, Repair Needed
 - Fireline Track Pile, Repair Needed
 - Fireline Needs Repair, Repair Needed
 - Fireline Needs Repair, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Crossing Location, Repair Needed
 - Water Crossing Location, Repair Needed
 - Waterline Needs Repair, Repair Needed
 - Waterline Needs Repair, Completed - Approved

SUPPRESSION REPAIR, 09/07/18
Div J

SoCal IMT 3 GIS
September 06, 2018
1850

QR Code

Miles
0 0.25 0.5 1

Datum: NAD 83



Mendocino Complex
CA-MEU-008674
September 7, 2018
SUPPRESSION REPAIR
Div J

- Repair Legend**
- Completed - Inspected
 - Completed - Ready for Inspection
 - In Progress
 - No Repair Needed
 - Other - See Comments
 - Repair Needed
 - Unknown
- Ownership**
- Other State Lands
 - USDA Forest Service
 - Bureau of Reclamation
 - Bureau of Land Management
 - Other Federal Lands
- Other Symbols:**
- Contained Fire Edge
 - Completed Dozer Line
 - Completed Hand Line
 - Road as Completed Line
 - Direct Protection Areas
 - Wilderness Area
 - Rehab Avoidance Area

Road Class shown in fuchsia. Not all roads show Road Class values.