



- Suppression Repair Points**
- PointType, Repair Status
 - Bridge, Repair Needed
 - Chipping Blank, Repair Needed
 - Culvert Damage, Completed - Approved
 - Culvert Damage, Repair Needed
 - Cover Push, Repair Needed
 - Cover Push, Completed - Approved
 - Drop Point, Repair Needed
 - Drop Point, Completed - Approved
 - Equipment Found, Repair Needed
 - Force Change, Repair Needed
 - Force Change, Completed - Approved
 - Gate, Repair Needed
 - Gate, Completed - Approved
 - Hazard Tree, Repair Needed
 - Hazard Tree, Repair Needed
 - Lip and Scatter Trees, Repair Needed
 - Mechanics Change, Repair Needed
 - Other - Repair
 - Other - Repair Needed
 - Other - Completed - Approved
 - Palisade Track Pile, Repair Needed
 - Palisade Track Pile, Repair Needed
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Drafting Location, Repair Needed
 - Water Drafting Location, Completed - Approved
 - Water Needs Repair, Repair Needed
 - Water Needs Repair, Completed - Approved

SoCal IMT 3 GIS
September 06, 2018
1854

QR Code

Miles

Datum: NAD 83



Mendocino Complex
CA-MEU-008674
September 7, 2018
SUPPRESSION REPAIR
Div K

- Repair Legend**
- Completed - Inspected
 - Completed - Ready for Inspection
 - In Progress
 - No Repair Needed
 - Other - See Comments
 - Repair Needed
 - Unknown

- Ownership**
- Other State Lands
 - USDA Forest Service
 - Bureau of Reclamation
 - Bureau of Land Management
 - Bureau of Indian Affairs
 - Other Federal Lands

- Ownership**
- Uncontrolled Fire Edge
 - Controlled Fire Edge
 - Completed Dozer Line
 - Completed Hand Line
 - Road as Completed Line
 - Bridge (w/ weight limit)
 - Direct Protection Areas
 - Wilderness Area
 - Rehab Avoidance Area

Road Class shown in fuchsia. Not all roads show Road Class values