



- Suppression Repair Points**
- Point Type: Repair Status
  - Repair Status: Repair Needed, Completed - Approved
  - Repair Type: Ridge, Chipping Blows, Culvert Damage, Clear Push, Drop Pile, Equipment Failure, Fence Damage, Gate, Hole, Lake, Hazard Tree, Log and Scatter Trees, Machine Damage, Other, Other, Roadbed Track, Road Needs Repair, Road Needs Repair, Water Course Crossing, Water Crossing Location, Waterstar

SUPPRESSION REPAIR, 09/08/18  
Div H

SoCal IMT 3 GIS  
September 07, 2018  
1999

Miles  
0 0.25 0.5 1

Datum: NAD 83



**Mendocino Complex**  
CA-MEU-008674  
September 8, 2018  
**SUPPRESSION REPAIR**  
Div H

- Repair Legend**
- Completed - Inspected
  - Completed - Ready for Inspection
  - In Progress
  - No Repair Needed
  - Other - See Comments
  - Repair Needed
  - Unknown
- Ownership**
- USDA Forest Service
- Other Symbols**
- Contained Fire Edge
  - Completed Dozer Line
  - Completed Hand Line
  - Road as Completed Line
  - Bridge (w/ weight limit)
  - Direct Protection Areas
  - Wilderness Area
  - Rehab Avoidance Area

Road Class shown in fuchsia. Not all roads show Road Class values