



- Suppression Repair Points**
- Point Type, Repair Status
  - Ridge, Repair Needed
  - Chopping Blows, Repair Needed - Approved
  - Culvert Damage, Repair Needed
  - Culvert Damage, Completed - Approved
  - Clear Push, Repair Needed
  - Clear Push, Completed - Approved
  - Clear Pile, Repair Needed
  - Clear Pile, Completed - Approved
  - Drop Point, Repair Needed
  - Equipment Fault, Repair Needed
  - Excavation, Repair Needed
  - Fence Damage, Repair Needed - Approved
  - Fence Damage, Completed - Approved
  - Gate, Repair Needed
  - Gate, Completed - Approved
  - Hazard Tree, Repair Needed
  - Hazard Tree, Repair Needed
  - Log and Scatter Trees, Repair Needed
  - Machine Damage, Repair Needed
  - Other, Repair Needed
  - Other, Completed - Approved
  - Relocation Truck, Repair Needed
  - Road Needs Repair, Repair Needed
  - Road Needs Repair, Completed - Approved
  - Water Course Crossing, Repair Needed
  - Water Course Crossing, Completed - Approved
  - Water Course Crossing, Repair Needed
  - Water Course Crossing, Completed - Approved
  - Watering Location, Repair Needed
  - Watering Location, Repair Needed
  - Watering Location, Completed - Approved
  - Watering Location, Completed - Approved

SUPPRESSION REPAIR\_09/08/18  
Div I

SoCal IMT 3 GIS  
September 07, 2018  
2003

Miles  
0 0.25 0.5 1

Datum: NAD 83



**Mendocino Complex**  
CA-MEU-008674  
September 8, 2018  
**SUPPRESSION REPAIR**  
Div I

- Repair Legend**
- Completed - Inspected
  - Completed - Ready for Inspection
  - In Progress
  - No Repair Needed
  - Other - See Comments
  - Repair Needed
  - Unknown
- Ownership**
- USDA Forest Service
  - Bureau of Reclamation
  - Bureau of Land Management
  - Bureau of Indian Affairs
  - Other Federal Lands
- Other Symbols:**
- Contained Fire Edge
  - Completed Dozer Line
  - Completed Hand Line
  - Road as Completed Line
  - Direct Protection Areas
  - Rehab Avoidance Area

Road Class shown in fuschia. Not all roads show Road Class values