



- Suppression Repair Points**
- PointType, Repair Status
- Ridge, Repair Needed
  - Chipping Blows, Repair Needed
  - Culvert Damage, Completed - Approved
  - Culvert Damage, Repair Needed
  - Clear Push, Repair Needed
  - Clear Push, Completed - Approved
  - Drop Point, Repair Needed
  - Drop Point, Completed - Approved
  - Equipment Fault, Repair Needed
  - Fence Damage, Repair Needed
  - Fence Damage, Completed - Approved
  - Gate, Repair Needed
  - Gate, Completed - Approved
  - Hazard Tree, Repair Needed
  - Hazard Tree, Repair Needed
  - Log and Scatter Trees, Repair Needed
  - Machine Damage, Repair Needed
  - Other, Repair Needed
  - Other, Completed - Approved
  - Roadwork Track Pile, Repair Needed
  - Roadwork Track Pile, Repair Needed
  - Road Needs Repair, Repair Needed
  - Road Needs Repair, Completed - Approved
  - Water Course Crossing, Repair Needed
  - Water Course Crossing, Repair Needed
  - Water Course Crossing, Completed - Approved
  - Water Crossing Location, Repair Needed
  - Watercourse Needs, Repair Needed
  - Watercourse Needs, Completed - Approved

Road Class shown in fuchsia. Not all roads show Road Class values

SUPPRESSION REPAIR\_09/08/18



Datum: NAD 83



**Mendocino Complex**  
 CA-MEU-008674  
 September 8, 2018  
**SUPPRESSION REPAIR**  
 Div J

**Repair Legend**

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

**Ownership**

- Contained Fire Edge
- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Direct Protection Areas
- Wilderness Area
- Rehab Avoidance Area
- Other State Lands
- USDA Forest Service
- Bureau of Reclamation
- Bureau of Land Management
- Other Federal Lands