


- Suppression Repair Points**
- Point Type: Repair Station
 - Ridge: Repair Needed
 - Chipping Blank: Repair Needed
 - Chipping Blank: Completed - Approved
 - Coastal Damage: Repair Needed
 - Coastal Damage: Completed - Approved
 - Clean Pile: Repair Needed
 - Clean Pile: Completed - Approved
 - Drop Point: Repair Needed
 - Drop Point: Completed - Approved
 - Equipment Frame: Repair Needed
 - Force Damage: Repair Needed
 - Force Damage: Completed - Approved
 - Gate: Repair Needed
 - Gate: Completed - Approved
 - Hazard Tree: Repair Needed
 - Hazard Tree: Completed - Approved
 - Lip and Scatter Trees: Repair Needed
 - Machine Damage: Repair Needed
 - Other: Repair Needed
 - Other: Completed - Approved
 - Resistant Track Pile: Repair Needed
 - Road Needs Repair: Repair Needed
 - Road Needs Repair: Completed - Approved
 - Water Course Crossing: Repair Needed
 - Water Course Crossing: Completed - Approved
 - Water Course Crossing: Repair Needed
 - Water Course Crossing: Completed - Approved
 - Water Drafting Location: Repair Needed
 - Water Drafting Location: Completed - Approved
 - Waterbar: Repair Needed
 - Waterbar: Completed - Approved

Road Class shown in fuchsia. Not all roads show Road Class values

SUPPRESSION REPAIR: 09/10/18 Div D/E



SoCal IMT 3 GIS
September 09, 2018
2120

Miles
0 0.25 0.5 1
Datum: NAD 83



Mendocino Complex
CA-MEU-008674
September 10, 2018
SUPPRESSION REPAIR
Div D/E

Repair Legend

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

Ownership

- Contained Fire Edge
- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Bridge (w/ weight limit)
- Direct Protection Areas
- Wilderness Area
- Other State Lands
- USDA Forest Service