


- Suppression Repair Points**
- Point Type: Repair Status
 - Bridge: Repair Needed
 - Chopping Blank: Repair Needed
 - Chopping Blank: Completed - Approved
 - Clearcut Damage: Repair Needed
 - Clearcut Damage: Completed - Approved
 - Clear Push: Repair Needed
 - Clear Push: Completed - Approved
 - Deep Push: Repair Needed
 - Deep Push: Completed - Approved
 - Equipment Failure: Repair Needed
 - Equipment Failure: Completed - Approved
 - Fence Damage: Repair Needed
 - Fence Damage: Completed - Approved
 - Gate: Repair Needed
 - Gate: Completed - Approved
 - Hazard Tree: Repair Needed
 - Hazard Tree: Completed - Approved
 - Hayrack: Repair Needed
 - Hayrack: Completed - Approved
 - Lip and Scatter Trees: Repair Needed
 - Lip and Scatter Trees: Completed - Approved
 - Machine Damage: Repair Needed
 - Machine Damage: Completed - Approved
 - Other: Repair Needed
 - Other: Completed - Approved
 - Rehabilitated Track Point: Repair Needed
 - Rehabilitated Track Point: Completed - Approved
 - Road Needs Repair: Repair Needed
 - Road Needs Repair: Completed - Approved
 - Water Course Crossing: Repair Needed
 - Water Course Crossing: Completed - Approved
 - Water Course Crossing: Repair Needed
 - Water Course Crossing: Completed - Approved
 - Water Drafting Location: Repair Needed
 - Water Drafting Location: Completed - Approved
 - Waterbar: Repair Needed
 - Waterbar: Completed - Approved



Suppression Repair: 09/10/18
Div F/G

SoCal IMT 3 GIS
September 09, 2018
2131

Miles
0 0.25 0.5 1

Datum: NAD 83

Mendocino Complex
CA-MEU-008674
September 10, 2018
SUPPRESSION REPAIR
Div F/G

Repair Legend

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

Ownership

- USDA Forest Service
- Wilderness Area
- Rehab Avoidance Area
- Bridge (w/ weight limit)

Road Class shown in fuchsia. Not all roads show Road Class values