


- Suppression Repair Points**
- PointType, Repair Status
 - Ridge, Repair Needed
 - Chipping Blank, Repair Needed
 - Culvert Damage, Repair Needed
 - Culvert Damage, Completed - Approved
 - Cover Path, Repair Needed
 - Cover Path, Completed - Approved
 - Drop Point, Repair Needed
 - Drop Point, Completed - Approved
 - Equipment Found, Repair Needed
 - Equipment Found, Completed - Approved
 - Fence Damage, Repair Needed
 - Fence Damage, Completed - Approved
 - Gate, Repair Needed
 - Gate, Completed - Approved
 - Hazard Tree, Repair Needed
 - Hazard Tree, Repair Needed
 - Lap and Scarred Trees, Repair Needed
 - Mudflow Damage, Repair Needed
 - Other - Repair Needed
 - Other - Completed - Approved
 - Resistant Track Pile, Repair Needed
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Drifting Location, Repair Needed
 - Water Needs Repair, Repair Needed
 - Water Needs Repair, Completed - Approved



Road Class shown in fuchsia. Not all roads show Road Class values

Mendocino Complex
 CA-MEU-008674
 September 10, 2018
SUPPRESSION REPAIR
 Div K

- Repair Legend**
- Completed - Inspected
 - Completed - Ready for Inspection
 - In Progress
 - No Repair Needed
 - Other - See Comments
 - Repair Needed
 - Unknown
- Ownership**
- Other State Lands
 - USDA Forest Service
 - Bureau of Reclamation
 - Bureau of Land Management
 - Bureau of Indian Affairs
 - Other Federal Lands
- Other Symbols:**
- Uncontrolled Fire Edge
 - Contained Fire Edge
 - Completed Dozer Line
 - Completed Hand Line
 - Road as Completed Line
 - Bridge (w/ weight limit)
 - Direct Protection Areas
 - Wilderness Area
 - Rehab Avoidance Area

SUPPRESSION REPAIR, 09/10/18
 Div K

SoCal IMT 3 GIS
 September 09, 2018
 2133

QR Code

Miles
 0 0.25 0.5 1

Datum: NAD 83

SOUTHERN CALIFORNIA
 INTERAGENCY INCIDENT MANAGEMENT

FOREST SERVICE
 U.S. DEPARTMENT OF AGRICULTURE