


- Suppression Repair Points**
- Point Type, Repair Status
 - Bridge, Repair Needed
 - Chipping Blank, Repair Needed
 - Culvert Damage, Repair Needed
 - Culvert Damage, Completed - Approved
 - Clear Flush, Repair Needed
 - Clear Flush, Completed - Approved
 - Deep Pits, Repair Needed
 - Deep Pits, Completed - Approved
 - Equipment Failure, Repair Needed
 - Equipment Failure, Completed - Approved
 - Fence Damage, Repair Needed
 - Fence Damage, Completed - Approved
 - Gate, Repair Needed
 - Gate, Completed - Approved
 - Hazard Tree, Repair Needed
 - Hillside, Repair Needed
 - Log and Scatter Trees, Repair Needed
 - Mechanical Damage, Repair Needed
 - Other, Repair Needed
 - Other, Completed - Approved
 - Rebarbed Truck Pits, Repair Needed
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Needs Repair, Repair Needed
 - Water Needs Repair, Completed - Approved



SUPPRESSION REPAIR, 09/11/18
Div F/G

SoCal IMT 3 GIS
September 10, 2018
2133

Miles
0 0.25 0.5 1

Datum: NAD 83



Mendocino Complex
CA-MEU-008674
September 11, 2018
SUPPRESSION REPAIR
Div F/G

Repair Legend

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

Ownership

- USDA Forest Service
- Wilderness Area
- Rehab Avoidance Area
- Bridge (w/ weight limit)

Road Class shown in fuchsia. Not all roads show Road Class values