


- Suppression Repair Points**
- PointType, Repair Status
  - Bridge, Repair Needed
  - Chipping Blank, Repair Needed
  - Culvert Damage, Repair Needed
  - Culvert Damage, Completed - Approved
  - Clear Push, Repair Needed
  - Clear Push, Completed - Approved
  - Deep Push, Repair Needed
  - Equipment Failure, Repair Needed
  - Force Damage, Repair Needed
  - Force Damage, Completed - Approved
  - Gate, Repair Needed
  - Gate, Completed - Approved
  - Hazard Tree, Repair Needed
  - Hillside, Repair Needed
  - Log and Skid Trail, Repair Needed
  - Mechanical Damage, Repair Needed
  - Other, Repair Needed
  - Other, Completed - Approved
  - Restroom Truck Park, Repair Needed
  - Road Needs Repair, Repair Needed
  - Road Needs Repair, Completed - Approved
  - Water Course Crossing, Repair Needed
  - Water Course Crossing, Completed - Approved
  - Water Course Crossing, Other
  - Water Course Crossing, Repair Needed
  - Water Course Crossing, Completed - Approved
  - Water Course Location, Repair Needed
  - Water Needs, Repair Needed
  - Water Needs, Completed - Approved



Road Class shown in fuschia. Not all roads show Road Class values

SUPPRESSION REPAIR: 09/11/18  
Div I

SoCal IMT 3 GIS  
September 10, 2018  
2144

Miles  
0 0.25 0.5 1

Datum: NAD 83



**Mendocino Complex**  
CA-MEU-008674  
September 11, 2018  
**SUPPRESSION REPAIR**  
Div I

- Repair Legend**
- Completed - Inspected
  - Completed - Ready for Inspection
  - In Progress
  - No Repair Needed
  - Other - See Comments
  - Repair Needed
  - Unknown
- Ownership**
- USDA Forest Service
  - Bureau of Reclamation
  - Bureau of Land Management
  - Bureau of Indian Affairs
  - Other Federal Lands
- Other Symbols:**
- Contained Fire Edge
  - Completed Dozer Line
  - Completed Hand Line
  - Road as Completed Line
  - Direct Protection Areas
  - Rehab Avoidance Area