


- Suppression Repair Points**
- PointType, Repair Status
- Bridge, Repair Needed
  - Chipping Blank, Repair Needed
  - Culvert Damage, Completed - Approved
  - Culvert Damage, Repair Needed
  - Clear Pile, Repair Needed
  - Clear Pile, Completed - Approved
  - Equipment Found, Repair Needed
  - Fence Damage, Repair Needed
  - Fence Damage, Completed - Approved
  - Gate, Repair Needed
  - Gate, Completed - Approved
  - Hazard Tree, Repair Needed
  - Hazard Tree, Repair Needed
  - Log and Skid Trail, Repair Needed
  - Machine Damage, Repair Needed
  - Other, Repair Needed
  - Other, Completed - Approved
  - Roadside Truck Pile, Repair Needed
  - Road Needs Repair, Repair Needed
  - Road Needs Repair, Completed - Approved
  - Water Course Crossing, Repair Needed
  - Water Course Crossing, Completed - Approved
  - Water Crossing Location, Repair Needed
  - Water Needs Repair, Repair Needed
  - Water Needs Repair, Completed - Approved



Road Class shown in fuschia. Not all roads show Road Class values

SUPPRESSION REPAIR, 09/11/18  
Div K

SoCal IMT 3 GIS  
September 10, 2018  
2154

Miles  
0 0.25 0.5 1

Datum: NAD 83



**Mendocino Complex**  
CA-MEU-008674  
September 11, 2018  
**SUPPRESSION REPAIR**  
Div K

- Repair Legend**
- Completed - Inspected
  - Completed - Ready for Inspection
  - In Progress
  - No Repair Needed
  - Other - See Comments
  - Repair Needed
  - Unknown
- Ownership**
- Other State Lands
  - USDA Forest Service
  - Bureau of Reclamation
  - Bureau of Land Management
  - Bureau of Indian Affairs
  - Other Federal Lands
- Other Symbols**
- Uncontrolled Fire Edge
  - Contained Fire Edge
  - Completed Dozer Line
  - Completed Hand Line
  - Road as Completed Line
  - Bridge (w/ weight limit)
  - Direct Protection Areas
  - Wilderness Area
  - Rehab Avoidance Area