


- Suppression Repair Points**
- Point Type, Repair Status
 - Bridge Repair Needed
 - Chipping Blank Repair Needed
 - Chipping Blank, Completed - Approved
 - Covert Damage, Repair Needed
 - Covert Damage, Completed - Approved
 - Clear Flush, Repair Needed
 - Clear Flush, Completed - Approved
 - Clear Patch, Repair Needed
 - Clear Patch, Completed - Approved
 - Equipment Failure, Repair Needed
 - Equipment Failure, Completed - Approved
 - Fence Damage, Repair Needed
 - Fence Damage, Completed - Approved
 - Gate, Repair Needed
 - Gate, Completed - Approved
 - Harvest Tree, Repair Needed
 - Harvest Tree, Completed - Approved
 - Log and Scatter Trees, Repair Needed
 - Log and Scatter Trees, Completed - Approved
 - Mechanical Damage, Repair Needed
 - Mechanical Damage, Completed - Approved
 - Other, Repair Needed
 - Other, Completed - Approved
 - Rebarbed Track Flank, Repair Needed
 - Rebarbed Track Flank, Completed - Approved
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Cleaning, Repair Needed
 - Water Course Cleaning, Completed - Approved
 - Water Drafting Location, Repair Needed
 - Water Drafting Location, Completed - Approved
 - Waterline Repair, Repair Needed
 - Waterline Repair, Completed - Approved

Road Class shown in fuschia. Not all roads show Road Class values

SUPPRESSION REPAIR, 09/11/18
Div B/C



SoCal IMT 3 GIS
September 11, 2018
2354

Miles
0 0.25 0.5 1
Datum: NAD 83



Mendocino Complex
CA-MEU-008674
September 12, 2018
SUPPRESSION REPAIR
Div B/C

Repair Legend

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

Ownership

- Contained Fire Edge
- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Bridge (w/ weight limit)
- Active Mines (2010)
- Direct Protection Areas
- Other State Lands
- USDA Forest Service