



- Suppression Repair Points**
- Point Type: Repair Status
 - Bridge: Repair Needed
 - Chipping Blank: Repair Needed
 - Chipping Blank: Completed - Approved
 - Covert Damage: Repair Needed
 - Covert Damage: Completed - Approved
 - Clear Path: Repair Needed
 - Clear Path: Completed - Approved
 - Drop Pile: Repair Needed
 - Drop Pile: Completed - Approved
 - Equipment Found: Repair Needed
 - Equipment Found: Completed - Approved
 - Fence Damage: Repair Needed
 - Fence Damage: Completed - Approved
 - Gate: Repair Needed
 - Gate: Completed - Approved
 - Hazard Tree: Repair Needed
 - Hilltop: Repair Needed
 - Log and Scatter Trees: Repair Needed
 - Mechanical Damage: Repair Needed
 - Other: Repair Needed
 - Other: Completed - Approved
 - Rebarbed Truck Pile: Repair Needed
 - Road Needs Repair: Repair Needed
 - Road Needs Repair: Completed - Approved
 - Water Course Cleaning: Repair Needed
 - Water Course Cleaning: Completed - Approved
 - Water Drafting Location: Repair Needed
 - Water Drafting Location: Completed - Approved
 - Waterline: Repair Needed
 - Waterline: Completed - Approved

SUPPRESSION REPAIR: 09/11/18
Div D/E

SoCal IMT 3 GIS
September 12, 2018
0004

QR Code

Miles

0 0.25 0.5 1

Datum: NAD 83

INTERAGENCY INCIDENT MANAGEMENT

Mendocino Complex

CA-MEU-008674
September 12, 2018

SUPPRESSION REPAIR

Div D/E

- Repair Legend**
- Completed - Inspected
 - Completed - Ready for Inspection
 - In Progress
 - No Repair Needed
 - Other - See Comments
 - Repair Needed
 - Unknown

- Contained Fire Edge
- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Bridge (w/ weight limit)
- Direct Protection Areas
- Wilderness Area

- Ownership**
- Other State Lands
 - USDA Forest Service

Road Class shown in fuchsia. Not all roads show Road Class values