


- Suppression Repair Points**
- Point Type: Repair Station
  - Chipping Blank: Repair Needed
  - Chipping Blank: Completed - Approved
  - Covert Damage: Repair Needed
  - Covert Damage: Completed - Approved
  - Clear Push: Repair Needed
  - Clear Push: Completed - Approved
  - Drop Pile: Repair Needed
  - Drop Pile: Completed - Approved
  - Equipment Found: Repair Needed
  - Equipment Found: Completed - Approved
  - Fence Damage: Repair Needed
  - Fence Damage: Completed - Approved
  - Gate: Repair Needed
  - Gate: Completed - Approved
  - Hazard Tree: Repair Needed
  - Hazard Tree: Completed - Approved
  - Helispot: Repair Needed
  - Helispot: Completed - Approved
  - Log and Scatter Trees: Repair Needed
  - Log and Scatter Trees: Completed - Approved
  - Mechanical Damage: Repair Needed
  - Mechanical Damage: Completed - Approved
  - Other: Repair Needed
  - Other: Completed - Approved
  - Rebarbed Track Pile: Repair Needed
  - Rebarbed Track Pile: Completed - Approved
  - Road Needs Repair: Repair Needed
  - Road Needs Repair: Completed - Approved
  - Road Needs Repair: Completed - Approved
  - Water Course Cleaning: Repair Needed
  - Water Course Cleaning: Completed - Approved
  - Water Course Cleaning: Completed - Approved
  - Water Drafting Location: Repair Needed
  - Water Drafting Location: Completed - Approved
  - Waterline Needed: Repair Needed
  - Waterline Needed: Completed - Approved



SUPPRESSION REPAIR: 09/11/18  
Div F/G

SoCal IMT 3 GIS  
September 11, 2018  
2248

Miles  
0 0.25 0.5 1

Datum: NAD 83



**Mendocino Complex**  
CA-MEU-008674  
September 12, 2018  
**SUPPRESSION REPAIR**  
Div F/G

- Repair Legend**
- Completed - Inspected
  - Completed - Ready for Inspection
  - In Progress
  - No Repair Needed
  - Other - See Comments
  - Repair Needed
  - Unknown
- Ownership**
- USDA Forest Service
  - Wilderness Area
  - Rehab Avoidance Area
  - Bridge (w/ weight limit)

Road Class shown in fuchsia. Not all roads show Road Class values