



- Suppression Repair Points**
- Point Type: Repair Station
 - Ridge: Repair Needed
 - Chipping Blank: Repair Needed
 - Chipping Blank: Completed - Approved
 - Conduit Damage: Repair Needed
 - Conduit Damage: Completed - Approved
 - Clear Path: Repair Needed
 - Clear Path: Completed - Approved
 - Drop Point: Repair Needed
 - Drop Point: Completed - Approved
 - Equipment Failure: Repair Needed
 - Force Damage: Repair Needed
 - Force Damage: Completed - Approved
 - Fence Damage: Repair Needed
 - Fence Damage: Completed - Approved
 - Gate: Repair Needed
 - Gate: Completed - Approved
 - Hazard Tree: Repair Needed
 - Hazard Tree: Completed - Approved
 - Heliport: Repair Needed
 - Log and Scatter Trees: Repair Needed
 - Machine Damage: Repair Needed
 - Machine Damage: Completed - Approved
 - Other: Repair Needed
 - Other: Completed - Approved
 - Rebarbed Track Flank: Repair Needed
 - Rebarbed Track Flank: Completed - Approved
 - Road Needs Repair: Repair Needed
 - Road Needs Repair: Completed - Approved
 - Water Course Cleaning: Repair Needed
 - Water Course Cleaning: Completed - Approved
 - Water Drafting Location: Repair Needed
 - Water Drafting Location: Completed - Approved
 - Waterline: Repair Needed
 - Waterline: Completed - Approved

Road Class shown in fuchsia. Not all roads show Road Class value.

SUPPRESSION REPAIR: 09/11/18 Div J



Datum: NAD 83



Mendocino Complex
 CA-MEU-008674
 September 12, 2018
SUPPRESSION REPAIR
 Div J

Repair Legend

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Direct Protection Areas
- Wilderness Area
- Rehab Avoidance Area

Ownership

- Other State Lands
- USDA Forest Service
- Bureau of Reclamation
- Bureau of Land Management
- Other Federal Lands