

- Suppression Repair Points**
- Edge, Repair Needed
 - Chipping Blank, Repair Needed
 - Chipping Blank, Completed - Approved
 - Covert Damage, Repair Needed
 - Covert Damage, Completed - Approved
 - Clear Patch, Repair Needed
 - Clear Patch, Completed - Approved
 - Drop Point, Repair Needed
 - Drop Point, Completed - Approved
 - Equipment Found, Repair Needed
 - Equipment Found, Repair Needed
 - Force Damage, Repair Needed
 - Force Damage, Completed - Approved
 - Gate, Repair Needed
 - Gate, Completed - Approved
 - Hazard Tree, Repair Needed
 - Hazard Tree, Repair Needed
 - High Spot, Repair Needed
 - High Spot, Repair Needed
 - Log and Scatter Trees, Repair Needed
 - Mechanical Damage, Repair Needed
 - Other, Repair Needed
 - Other, Completed - Approved
 - Restoration Track Point, Repair Needed
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Clearing, Repair Needed
 - Water Course Clearing, Repair Needed
 - Water Course Clearing, Completed - Approved
 - Water Drafting Location, Repair Needed
 - Water Drafting Location, Repair Needed
 - Waterline, Repair Needed
 - Waterline, Completed - Approved

Repair Legend



- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

Ownership

- Other State Lands
- USDA Forest Service
- Bureau of Reclamation
- Bureau of Land Management
- Bureau of Indian Affairs
- Other Federal Lands

Mendocino Complex
 CA-MEU-008674
 September 12, 2018
SUPPRESSION REPAIR
 Div L

SUPPRESSION REPAIR, 09/11/18
 Div L



T16N R6W
 Road Class shown in fuchsia. Not all roads show Road Class values