



- Suppression Repair Points**
- Point Type, Repair Status
 - Bridge Repair Needed
 - Chipping Blank Repair Needed
 - Culvert Damage, Repair Needed
 - Culvert Damage, Completed - Approved
 - Clear Push, Repair Needed
 - Clear Push, Completed - Approved
 - Deep Pits, Repair Needed
 - Equipment Failure, Repair Needed
 - Force Damage, Repair Needed
 - Force Damage, Completed - Approved
 - Gate, Repair Needed
 - Gate, Completed - Approved
 - Hazard Tree, Repair Needed
 - Hillside, Repair Needed
 - Log and Section Trees, Repair Needed
 - Mechanical Damage, Repair Needed
 - Other, Repair Needed
 - Other, Completed - Approved
 - Reinforced Truck Pits, Repair Needed
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Drilling Location, Repair Needed
 - Water Needed, Repair Needed
 - Water Needed, Completed - Approved



Road Class shown in fuchsia. Not all roads show Road Class values

SUPPRESSION REPAIR, 09/13/18 Div F/G



Miles
0 0.25 0.5 1
Datum: NAD 83



Mendocino Complex
CA-MEU-008674
September 13, 2018
SUPPRESSION REPAIR
Div F/G

Repair Legend

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

Ownership

- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Bridge (w weight limit)
- Direct Protection Areas
- Wilderness Area
- Rehab Avoidance Area
- USDA Forest Service

SUPPRESSION REPAIR, 09/13/18 Div F/G