



Suppression Repair Points

Point Type, Repair Status

- Ridge, Repair Needed
- Chipping Blank, Repair Needed
- Chipping Blank, Completed - Approved
- Culvert Damage, Repair Needed
- Culvert Damage, Completed - Approved
- Clear Push, Repair Needed
- Clear Push, Completed - Approved
- Deep Pits, Repair Needed
- Deep Pits, Completed - Approved
- Equipment Pits, Repair Needed
- Fence Damage, Repair Needed
- Fence Damage, Completed - Approved
- Gate, Repair Needed
- Gate, Completed - Approved
- Hazard Tree, Repair Needed
- Hazard Tree, Completed - Approved
- Lip and Saddle Track, Repair Needed
- Mechanical Damage, Repair Needed
- Other, Repair Needed
- Other, Completed - Approved
- Rebar/Track Pits, Repair Needed
- Road Needs Repair, Repair Needed
- Road Needs Repair, Completed - Approved
- Water Course Crossing, Repair Needed
- Water Course Crossing, Completed - Approved
- Water Choking Location, Repair Needed
- Water Choking Location, Completed - Approved
- Weather Needs, Repair Needed
- Weather Needs, Completed - Approved

SUPPRESSION REPAIR, 09/13/18
Div H

SoCal IMT 3 GIS
September 13, 2018
2120

Miles
0 0.25 0.5 1

Datum: NAD 83



Mendocino Complex
CA-MEU-008674
September 13, 2018
SUPPRESSION REPAIR
Div H

Repair Legend

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

Ownership

- USDA Forest Service

Other Legend

- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Bridge (w/ weight limit)
- Direct Protection Areas
- Wilderness Area
- Rehab Avoidance Area

Road Class shown in fuchsia. Not all roads show Road Class values