



- Suppression Repair Points**
- PointType, Repair Status
  - Bridge, Repair Needed
  - Chipping Blank, Repair Needed
  - Culvert Change, Completed - Approved
  - Culvert Change, Repair Needed
  - Clear Push, Repair Needed
  - Clear Push, Completed - Approved
  - Drop Pile, Repair Needed
  - Drop Pile, Completed - Approved
  - Equipment Failure, Repair Needed
  - Flume Change, Repair Needed
  - Flume Change, Completed - Approved
  - Gate, Repair Needed
  - Gate, Completed - Approved
  - Hazard Tree, Repair Needed
  - Hazard Tree, Completed - Approved
  - Log and Scatter Trunk, Repair Needed
  - Mechanical Damage, Repair Needed
  - Other, Repair Needed
  - Other, Completed - Approved
  - Rebarbed Track Pile, Repair Needed
  - Road Needs Repair, Repair Needed
  - Road Needs Repair, Completed - Approved
  - Water Course Crossing, Repair Needed
  - Water Course Crossing, Completed - Approved
  - Water Course Crossing, Other
  - Water Course Crossing, Repair Needed
  - Water Course Crossing, Completed - Approved
  - Water Choking Location, Repair Needed
  - Water Choking Location, Completed - Approved
  - Water Needs Repair, Repair Needed
  - Water Needs Repair, Completed - Approved



Road Class shown in fuchsia. Not all roads show Road Class values

SUPPRESSION REPAIR, 09/13/18 Div I



SoCal IMT 3 GIS  
September 13, 2018  
2130

Miles  
0 0.25 0.5 1  
Datum: NAD 83



INTERAGENCY INCIDENT MANAGEMENT

**Mendocino Complex**  
CA-MEU-008674  
September 13, 2018  
**SUPPRESSION REPAIR**  
Div I

**Repair Legend**

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Direct Protection Areas
- Rehab Avoidance Area

**Ownership**

- USDA Forest Service
- Bureau of Reclamation
- Bureau of Land Management
- Bureau of Indian Affairs
- Other Federal Lands

SUPPRESSION REPAIR, 09/13/18 Div I