


- Suppression Repair Points**
- Point Type, Repair Status
  - Bridge Repair Needed
  - Chipping Blank Repair Needed
  - Chipping Blank, Completed - Approved
  - Culvert Damage, Repair Needed
  - Culvert Damage, Completed - Approved
  - Clear Flush, Repair Needed
  - Clear Flush, Completed - Approved
  - Clear Pile, Repair Needed
  - Clear Pile, Completed - Approved
  - Equipment Failure, Repair Needed
  - Equipment Failure, Completed - Approved
  - Flare Damage, Repair Needed
  - Flare Damage, Completed - Approved
  - Gate, Repair Needed
  - Gate, Completed - Approved
  - Hazard Tree, Repair Needed
  - Hilltop, Repair Needed
  - Log and Scatter Trees, Repair Needed
  - Machine Damage, Repair Needed
  - Other, Repair Needed
  - Other, Completed - Approved
  - Rebarbed Track Pile, Repair Needed
  - Rebarbed Track Pile, Completed - Approved
  - Road Needs Repair, Repair Needed
  - Road Needs Repair, Completed - Approved
  - Water Course Crossing, Repair Needed
  - Water Course Crossing, Completed - Approved
  - Water Course Location, Repair Needed
  - Water Course Location, Completed - Approved
  - Waterbar Repair, Repair Needed
  - Waterbar Repair, Completed - Approved



Road Class shown in fuchsia. Not all roads show Road Class values

**Mendocino Complex**  
 CA-MEU-008674  
 September 15, 2018  
 0600  
**SUPPRESSION REPAIR**  
 Div F/G

**Repair Legend**

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

**Ownership**

- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Bridge (w/ weight limit)
- Direct Protection Areas
- Wilderness Area
- Rehab Avoidance Area
- USDA Forest Service

SUPPRESSION REPAIR, 09/15/18  
 Div F/G

Miles  
 0 0.25 0.5 1

Datum: NAD 83

INTERAGENCY INCIDENT MANAGEMENT

SoCal IMT 3 GIS  
 September 14, 2018  
 2050