



- Suppression Repair Points**
- PointType, Repair Status
 - Bridge, Repair Needed
 - Chipping Blank, Repair Needed
 - Culvert Damage, Repair Needed
 - Culvert Damage, Completed - Approved
 - Clear Push, Repair Needed
 - Clear Push, Completed - Approved
 - Deep Push, Repair Needed
 - Equipment Failure, Repair Needed
 - Force Damage, Repair Needed
 - Force Damage, Completed - Approved
 - Gate, Repair Needed
 - Gate, Completed - Approved
 - Hazard Tree, Repair Needed
 - Hillside, Repair Needed
 - Log and Scatter Trees, Repair Needed
 - Mechanical Damage, Repair Needed
 - Other, Repair Needed
 - Other, Completed - Approved
 - Rebarbed Track Piles, Repair Needed
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Clearing, Repair Needed
 - Water Course Clearing, Completed - Approved
 - Water Course Clearing, Other
 - Water Course Clearing, Repair Needed
 - Water Course Clearing, Completed - Approved
 - Water Drafting Location, Repair Needed
 - Water Drafting Location, Completed - Approved
 - Water Needs, Repair Needed
 - Water Needs, Completed - Approved



Road Class shown in fuchsia. Not all roads show Road Class values

SUPPRESSION REPAIR, 09/15/18 Div I



SoCal IMT 3 GIS
September 14, 2018
211

Miles
0 0.25 0.5 1
Datum: NAD 83



INTERAGENCY INCIDENT MANAGEMENT

Mendocino Complex

CA-MEU-008674
September 15, 2018
0600
SUPPRESSION REPAIR
Div I

Repair Legend

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Direct Protection Areas
- Rehab Avoidance Area

Ownership

- USDA Forest Service
- Bureau of Reclamation
- Bureau of Land Management
- Bureau of Indian Affairs
- Other Federal Lands

SUPPRESSION REPAIR, 09/15/18 Div I