



- Suppression Repair Points**
- PointType, Repair Status
 - Ridge, Repair Needed
 - Chipping Blank, Repair Needed
 - Culvert Damage, Completed - Approved
 - Culvert Damage, Repair Needed
 - Clear Patch, Repair Needed
 - Clear Patch, Completed - Approved
 - Deep Pits, Repair Needed
 - Equipment Pits, Repair Needed
 - Fence Damage, Repair Needed
 - Fence Damage, Completed - Approved
 - Gate, Repair Needed
 - Gate, Completed - Approved
 - Hazard Tree, Repair Needed
 - Hilltop, Repair Needed
 - Log and Scatter Trees, Repair Needed
 - Mechanical Damage, Repair Needed
 - Other, Repair Needed
 - Other, Completed - Approved
 - Restroom Truck Pits, Repair Needed
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Drafting Location, Repair Needed
 - Water Drafting Location, Completed - Approved
 - Waterbar Repair, Repair Needed
 - Waterbar Repair, Completed - Approved

SUPPRESSION REPAIR, 09/15/18
Div L

SoCal IMT 3 GIS
September 14, 2018
2147

Miles
0 0.25 0.5 1

Datum: NAD 83



Mendocino Complex

CA-MEU-008674
September 15, 2018
0600
SUPPRESSION REPAIR
Div L

- Repair Legend**
- Completed - Inspected
 - Completed - Ready for Inspection
 - In Progress
 - No Repair Needed
 - Other - See Comments
 - Repair Needed
 - Unknown
- Ownership**
- Other State Lands
 - USDA Forest Service
 - Bureau of Reclamation
 - Bureau of Land Management
 - Bureau of Indian Affairs
 - Other Federal Lands
- Other Symbols**
- Uncontrolled Fire Edge
 - Completed Dozer Line
 - Completed Hand Line
 - Road as Completed Line
 - Bridge (w/ weight limit)
 - Direct Protection Areas
 - Wilderness Area
 - Rehab Avoidance Area