



- Suppression Repair Points**
- Point Type, Repair Status
 - Ridge, Repair Needed
 - Chipping Blank, Repair Needed
 - Chipping Blank, Completed - Approved
 - Covert Damage, Repair Needed
 - Covert Damage, Completed - Approved
 - Cover Flush, Repair Needed
 - Cover Flush, Completed - Approved
 - Drop Point, Repair Needed
 - Drop Point, Completed - Approved
 - Equipment Fording, Repair Needed
 - Equipment Fording, Completed - Approved
 - Fence Damage, Repair Needed
 - Fence Damage, Completed - Approved
 - Gate, Repair Needed
 - Gate, Completed - Approved
 - Hazard Tree, Repair Needed
 - Hazard Tree, Repair Needed
 - Log and Scatter Trees, Repair Needed
 - Machine Damage, Repair Needed
 - Other, Repair Needed
 - Other, Completed - Approved
 - Rebarbed Track Floor, Repair Needed
 - Rebarbed Track Floor, Completed - Approved
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Crossing Location, Repair Needed
 - Water Crossing Location, Completed - Approved
 - Waterstar Needed, Repair Needed
 - Waterstar Needed, Completed - Approved

Road Class shown in fuchsia. Not all roads show Road Class values

Mendocino Complex
 CA-MEU-008674
 September 17, 2018
SUPPRESSION REPAIR
 Div H

- Repair Legend**
- Completed - Inspected
 - Completed - Ready for Inspection
 - In Progress
 - No Repair Needed
 - Other - See Comments
 - Repair Needed
 - Unknown
- Ownership**
- Completed Dozer Line
 - Completed Hand Line
 - Road as Completed Line
 - Bridge (w weight limit)
 - Direct Protection Areas
 - Wilderness Area
 - Rehab Avoidance Area
 - USDA Forest Service

SUPPRESSION REPAIR, 09/17/18
 Div H

SoCal IMT 3 GIS
 September 16, 2018
 2152

Miles
 0 0.25 0.5 1

Datum: NAD 83

