


- Suppression Repair Points**  
 PointType, Repair Status
- Bridge, Repair Needed
  - Chipping Blank, Repair Needed
  - Culvert Damage, Completed - Approved
  - Culvert Damage, Repair Needed
  - Debris Pile, Repair Needed
  - Debris Pile, Completed - Approved
  - Drop Point, Repair Needed
  - Equipment Failure, Repair Needed
  - Fence Damage, Repair Needed
  - Fence Damage, Completed - Approved
  - Gate, Repair Needed
  - Gate, Completed - Approved
  - Hazard Tree, Repair Needed
  - Helicopter, Repair Needed
  - Log and Scatter Trees, Repair Needed
  - Machine Damage, Repair Needed
  - Other, Repair Needed
  - Other, Completed - Approved
  - Roadblock Truck Flip, Repair Needed
  - Roadblock Truck Flip, Repair Needed
  - Road Needs Repair, Repair Needed
  - Road Needs Repair, Completed - Approved
  - Water Course Crossing - High, Repair Needed
  - Water Course Crossing, Repair Needed
  - Water Course Crossing, Completed - Approved
  - Water Crossing Location, Repair Needed
  - Water Needed, Repair Needed
  - Water Needed, Completed - Approved



Road Class shown in fuschia. Not all 16 roads show Road Class values

SoCal IMT 3 GIS  
 September 16, 2018  
 2156

Datum: NAD 83

Scale: 0 0.25 0.5 1 Miles



**Mendocino Complex**  
 CA-MEU-008674  
 September 17, 2018  
**SUPPRESSION REPAIR**  
 Div I

- Repair Legend**
- Completed - Inspected
  - Completed - Ready for Inspection
  - In Progress
  - No Repair Needed
  - Other - See Comments
  - Repair Needed
  - Unknown
- Ownership**
- USDA Forest Service
  - Bureau of Reclamation
  - Bureau of Land Management
  - Bureau of Indian Affairs
  - Other Federal Lands
- Other Symbols**
- Completed Dozer Line
  - Completed Hand Line
  - Road as Completed Line
  - Direct Protection Areas
  - Rehab Avoidance Area

SUPPRESSION REPAIR, 09/17/18  
Div I

SUPPRESSION REPAIR, 09/17/18  
Div I