


- Suppression Repair Points**
- PointType, Repair Status
 - Bridge Repair Needed
 - Chipping Blank Repair Needed
 - Chipping Blank, Completed - Approved
 - Clearing Damage, Repair Needed
 - Clearing Damage, Completed - Approved
 - Cover Flush, Repair Needed
 - Cover Flush, Completed - Approved
 - Deep Pore, Repair Needed
 - Deep Pore, Completed - Approved
 - Equipment Failure, Repair Needed
 - Equipment Failure, Completed - Approved
 - Fence Damage, Repair Needed
 - Fence Damage, Completed - Approved
 - Gate, Repair Needed
 - Gate, Completed - Approved
 - Harvest Tree, Repair Needed
 - Harvest Tree, Completed - Approved
 - Log and Scatter Trees, Repair Needed
 - Log and Scatter Trees, Completed - Approved
 - Machine Damage, Repair Needed
 - Machine Damage, Completed - Approved
 - Other, Repair Needed
 - Other, Completed - Approved
 - Rebar/Track Flare, Repair Needed
 - Rebar/Track Flare, Completed - Approved
 - Reel Needs Repair, Repair Needed
 - Reel Needs Repair, Completed - Approved
 - Water Course Closing - High
 - Water Course Closing, Repair Needed
 - Water Course Closing, Completed - Approved
 - Water Choking Location, Repair Needed
 - Water Choking Location, Completed - Approved
 - Waterer Needed, Repair Needed
 - Waterer Needed, Completed - Approved



Road Class shown in fuchsia. Not all roads show Road Class values

SUPPRESSION REPAIR, 09/18/18
Div B/C

SoCal IMT 3 GIS
September 17, 2018
2256

Miles
0 0.25 0.5 1

Datum: NAD 83



Mendocino Complex
CA-MEU-008674
September 18, 2018
SUPPRESSION REPAIR
Div B/C

- Repair Legend**
- Completed - Inspected
 - Completed - Ready for Inspection
 - In Progress
 - No Repair Needed
 - Other - See Comments
 - Repair Needed
 - Unknown
- Ownership**
- Other State Lands
 - USDA Forest Service
- Other Symbols**
- Completed Dozer Line
 - Completed Hand Line
 - Road as Completed Line
 - Bridge (w/ weight limit)
 - Active Mines (2010)
 - Direct Protection Areas

SUPPRESSION REPAIR, 09/18/18
Div B/C

SUPPRESSION REPAIR, 09/18/18
Div B/C